Mile High Flood District ALERT Network 2020 End of Year Report



Prepared for: Kevin Stewart Mile Hight Flood District Denver, Colorado

Prepared by: Water & Earth Technologies, Inc. 1225 Red Cedar Circle, Suite A Fort Collins, CO 80524 (970) 225-6080



Contents

1.	Intr	oduction	. 1
2.		nitoring Network	
		-	
3.	Ма	intenance Activities	. 1
	3.1	Arvada Blunn (ID: 10022)	2
	3.2	Weir Gulch (ID: 10032)	3
	3.3	Brantner Gulch (ID:10041)	4
	3.4	Big Dry Creek at Thorncreek (ID: 10042)	5
	3.5	Coal Creek at Twin Spruce (ID: 10049)	6
	3.6	Upper Coal Creek at Camp Eden Rd (ID: 10050)	7
4.	Con	nclusion	٤ .
5.	Spa	re Equipment Inventory	٤ .
6.	Rec	ommendations	. ٤
7.	Apr	pendix A. Site Specific Maintenance Records	. 9



1. Introduction

This report summarizes the field maintenance activities conducted in 2020 by Water & Earth Technologies, Inc. (WET) under contract to the Mile High Flood District (District) for the Real-Time Flood Detection System.

The maintenance records are generated from the maintenance software Fast Field Forms and are provided in Appendix A.

2. Monitoring Network

Through 2020 WET maintained six stations in the UDFCD network which included Arvada Blunn Reservoir (10022), Weir Gulch (10032), Brantner Gulch (10041), Big Dry Creek at Thorncreek (10042), Upper Coal Creek at Camp Eden Road (10050), and Coal Creek at Twin Spruce (10049).

The system was inspected and activated in March and was operational from April 1 to October 23. The rain and stage stations were shut down and winterized in October with Weir Gulch (10032), Upper Coal Creek at Camp Eden Road (10050), and Coal Creek at Twin Spruce Rd (10049) transmitters being stored at the WET office.

3. Maintenance Activities

Full maintenance activities are performed during each visit. The top section of each ALERT rain gage standpipe assembly is removed to clean the screen, funnel, and tipping bucket. The tipping buckets are leveled; standpipes and other appurtenances are painted to protect against corrosion and vandalism; antenna mounts, clamps, cables, and conduits are secured; and each site is inspected to meet the terms of existing license agreements or varying field conditions. The radio and antenna system are tested. The battery is checked. Test transmissions are performed to assure that gage reports are being received by ALERT base stations. Pressure transducer (PT) orifices and protective housings are checked and maintained free of mud and debris. Pressure tests are performed on all accessible PT's. Transmitted data are recorded and compared with calibration tables. All defective equipment is repaired or replaced as needed using available spare parts. Calibration adjustments are made as needed.

A summary of maintenance work performed at each location is provided in the following sections. Detailed maintenance records are provided in the appendix.



3.1 Arvada Blunn (ID: 10022)

The radar at Arvada Blunn is left running year-round to monitor the water level at Blunn Reservoir. The station was inspected on April 24th. All equipment was checked, cleaned and tested. All equipment was in working order. The radar and staff gage values matched.

Mid-season inspections were conducted on June 30th and August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

Since there is only a radar at this station, the station is left running year-round.



Figure 3-1: Arvada Blunn (10022) radar

Table 3-1: Arvada Blunn Maintenance Summary

			Bat	tery Volta	age	Solar Re	gulator		Radio	
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(V)	(V)	(V)	(V)	(mA)	(W)	(W)	
	Arvada	4/24/2020	13.27	13.18	0.09	21.38	149	4.00	0.25	1.67
10022	Blunn	6/30/2020	13.20	13.11	0.09	21.53	582	4.50	0.25	1.62
	Reservoir	8/26/2020	13.40	13.18	0.22	14.06	288	4.00	0.25	1.67



3.2 Weir Gulch (ID: 10032)

The station at Weir Gulch was activated on March 18th. All equipment was checked, cleaned, and tested. All equipment was in working order. The intake was full of sediment causing no water to get into the riser. The intake was flushed of all sediment.

Mid-season inspections were conducted on June 20th and August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

On October 23rd, winter shut-down activities were performed. All equipment was checked, cleaned and tested. The transmitter was removed, and the PT was pulled up into its winter position. All equipment was in working order.



Figure 3-2: Weir Gulch Station

Table 3-2: Weir Gulch Maintenance Summary

			Ba	ttery Volta	age	Solar R	egulator	Radio		
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(v)	(V)	(V)	(V)	(mA)	(W)	(W)	
		3/18/2020	12.91	12.81	0.10	14.25	37	3.25	0.00	1.00
10032	Weir Gulch	6/20/2020	13.43	13.37	0.06	14.32	26	3.75	0.10	1.39
		8/26/2020	13.49	13.40	0.09	13.93	280	3.90	0.00	1.00



3.3 Brantner Gulch (ID:10041)

The station at Brantner Gulch was activated on March 18th. All equipment was checked, cleaned and tested. All equipment was in working order.

Mid-season inspections were conducted on June 9th and August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

On October 23rd, winter shut-down activities were performed. The PT was pulled up into its winter position and the battery was brought back to be charged. The top section was also brought back for repairs to the base and was reinstalled.



Figure 3-3: Brantner Gulch near Syracuse St

Table 3-3: Brantner Gulch near Syracuse St Maintenance Summary

			Bat	tery Volta	age	Solar Ro	egulator		Radio	
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(v)	(V)	(V)	(V)	(mA)	(W)	(W)	
	D.	3/18/2020	12.69	12.63	0.06	21.69	267	4.50	0.10	1.35
10041	Brantner Gulch	6/9/2020	13.59	13.47	0.12	11.94	71	4.25	0.10	1.36
	Guich	8/26/2020	13.27	13.16	0.11	14.11	157	4.50	0.00	1.00



3.4 Big Dry Creek at Thorncreek (ID: 10042)

The station at Big Dry Creek at Thorncreek was activated on March 18th. All equipment was checked, cleaned and tested. All equipment was in working order.

Mid-season inspections were conducted on June 21st and August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

On October 23rd, winter shut-down activities were performed. The PT was pulled up into its winter position, tipping bucket was covered, and the battery was brought back to be charged over winter.



Figure 3-4: Big Dry Creek at Thorncreek Golf Course

Table 3-4: Big Dry Creek at Thorncreek Golf Course Maintenance Summary

			Bat	tery Volt	age	Solar Ro	egulator		Radio	
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(v)	(V)	(V)	(V)	(mA)	(W)	(W)	
	Big Dry	3/18/2020	12.90	12.81	0.09	14.22	56	4.25	0.25	1.64
10042	Creek @	6/21/2020	13.97	13.85	0.12	14.01	49	4.00	0.10	1.38
	Thorncreek	8/26/2020	13.44	13.29	0.15	13.97	162	4.25	0.10	1.36

5



3.5 Coal Creek at Twin Spruce (ID: 10049)

The station Coal Creek at Twin Spruce was activated on March 18th. All equipment was checked, cleaned and tested. The SDI-12 PT was not reading correctly so a 6-point calibration was executed, and a -0.63 offset was programmed which keeps growing. All equipment was in working order.

A mid-season inspection was conducted on June 30th. The PT was recalibrated to an offset of -0.21. All other equipment was in working order.

The second mid-season inspection took place on August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

On October 23rd, winter shut-down activities were performed. The PT was pulled up into its winter position and the transmitter was removed to be stored at the WET office.



Figure 3-5: Coal Creek at Twin Spruce

Table 3-5: Coal Creek at Twin Spruce Maintenance Summary

			Bat	tery Volt	age	Solar Ro	egulator		Radio	
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(V)	(V)	(V)	(V)	(mA)	(W)	(W)	
	Coal	3/18/2020	12.64	12.58	0.06	14.71	38	5.00	0.10	1.33
10049	Creek @ Twin	6/30/2020	12.81	12.74	0.07	14.65	42	5.00	0.00	1.00
	Spruce	8/26/2020	12.96	12.86	0.10	13.52	98	4.50	0.00	1.00



3.6 Upper Coal Creek at Camp Eden Rd (ID: 10050)

The station Upper Coal Creek at Camp Eden Rd was activated on March 18th. All equipment was checked, cleaned and tested. All equipment was in working order.

Mid-season inspections were conducted on June 23rd and August 26th. All equipment was checked, cleaned and tested. All equipment was in working order.

On October 23rd, winter shut-down activities were performed. The transmitter was removed to be stored at the WET office.



Figure 3-6: Upper Coal Creek at Camp Eden Road

Table 3-6: Upper Coal Creek at Camp Eden Road Maintenance Summary

				Battery Voltage			egulator	Radio		
Sta. No.	Station Name	Date	Quiet	Load	Delta	Output Voltage	Output Current	FWD	REF	SWR
			(v)	(V)	(V)	(V)	(mA)	(W)	(W)	
	Upper Coal	3/18/2020	12.82	12.77	0.05	14.69	161	5.00	0.10	1.33
10050	Creek @	6/23/2020	13.65	13.59	0.06	14.42	211	5.00	0.00	1.00
	Camp Eden	8/26/2020	13.68	13.60	0.08	14.29	166	4.50	0.00	1.00



4. Conclusion

All UDFCD sites are up to date and working correctly. These stations will be visited for maintenance three times during the 2021 season: March start-up and two mid-season maintenance visits. WET will clean PT's in vinegar on each site visit to try and resolve the constant offset changes especially at Twin Spruce. The creek seems to be iron rich causing the PT casement to turn reddish. Letting the PT sit in vinegar should clean away the discoloration and clean the membrane. If the PT continues to have fluctuating offsets it may need to be replaced due to the PT going bad.

5. Spare Equipment Inventory

- (1) 300 mA solar panel
- (1) Polyphaser lightning protection
- (1) Solar panel mount
- (1) GPS antenna
- (1) MaxRad 5800 DC grounded antenna
- (1) Sunguard Solar regulator
- (1) MaxRad antenna base mount

Prior to the 2021 maintenance season, WET recommends the purchase of the following spare equipment:

- (1) Maxon SD-125E radio \$300 ea.
- (1) Campbell Scientific AL200 \$550 ea.
- (1) 18 Ah battery \$90 ea
- (1) CS451 Pressure Transducer- \$875 ea.

6. Recommendations

WET recommends making periodic manual streamflow measurements at these locations in 2021 to supplement the theoretical ratings. WET also recommends the purchase of a spare CS451 SDI-12 pressure transducer in case the PT at Twin Spruce fails.



7. Appendix A. Site Specific Maintenance Records





Station Maintenance Form

Location	Arvada Blunn
Station_ID	10022
Technician(s)	Kgs
Date	04/24/2020
Time Arrive	11:50 AM (-6 GMT)
GPS Location	© mapbox © Mapbox, © OpenStreetMap
	Lat: 39.8226656283389 Long: -105.204460766956
Agency	UDFCD

Station Type

What type of station? Stream

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station has sensor?	ve a rain	No



Error (%)	0.27
-----------	------

Power System

Regulator Output Voltage (V)	21.38
Charging Current (mA)	149.00
Battery Voltage Quiet (V)	13.27
Battery Voltage Transmitted (V)	13.18

Transmitter

Trans	mitter Checks	Desiccant, Program, Time
Halls	IIIILLEI CHECKS	Desiccant, Flogram, Time

Radio

Watts Forward	4.00
Watts Reflected	0.25
Standing Wave Ratio	1.6667
No calibration form necessary	Check to see if PT is working properly.

Radar Calibration

Section 1

Calibration Time	12:00 PM (-6 GMT)
Wire-Weight Reading (ft)	55.25
Radar Reading (ft)	5755.35
Adjustment amount	0.00
Comments	Radar working well!

Note for next visit	Gary Williamson no longer works with the city.
Final Comments	Station working well!
Depart Time	12:20 PM (-6 GMT)



Photos









Station Maintenance Form

Location	Arvada Blunn
Station_ID	10022
Technician(s)	ZJN,KGS
Date	06/30/2020
Time Arrive	11:21 AM (-6 GMT)
GPS Location	
	Lat: 39.822941 Long: -105.2048702
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Rain Sensor

Does the station have a rain sensor?	No
--------------------------------------	----

Rain Gage Calibration

Error (%)	0.27
-----------	------

Power System



Regulator Output Voltage (V)	21.53
Charging Current (mA)	582.00
Battery Voltage Quiet (V)	13.20
Battery Voltage Transmitted (V)	13.11

Transmitter

|--|

Radio

Watts Forward	4.50
Watts Reflected	0.25
Standing Wave Ratio	1.6168
No calibration form necessary	Check to see if PT is working properly.

Radar Calibration

Section 1

Calibration Time	11:27 AM (-6 GMT)
Wire-Weight Reading (ft)	5763.00
Radar Reading (ft)	5763.03
Comments	prefect

Final Comments	Everything working well. Received test transmissions. Radar spot on
Depart Time	11:30 AM (-6 GMT)
Photos	







Station Maintenance Form

Station Maintenance Fo	
Location	Arvada Blunn
Station_ID	10022
Technician(s)	EJH/ZJN
Date	08/26/2020
Time Arrive	11:58 AM (-6 GMT)
GPS Location	
	② mapbox © Mapbox, © OpenStreetMap
	Lat: 39.8229108 Long: -105.2048271
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Solar_panel
--------------	-------------

Rain Sensor

Does the station have a rain sensor?	No



Error (%)	0.27

Power System

Regulator Output Voltage (V)	14.06
Charging Current (mA)	288.00
Battery Voltage Quiet (V)	13.40
Battery Voltage Transmitted (V)	13.18

Transmitter

Transmitter Checks

Radio

Watts Forward	4.00
Watts Reflected	0.25
Standing Wave Ratio	1.6667
No calibration form necessary	Check to see if PT is working properly.

Radar Calibration

Section 1

Calibration Time	12:01 PM (-6 GMT)
Wire-Weight Reading (ft)	5761.25
Radar Reading (ft)	5761.25

Depart Time	12:02 PM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance Fo	7111
Location	Weir Gulch
Station_ID	10032
Technician(s)	EJH/ZJN
Date	08/26/2020
Time Arrive	12:41 PM (-6 GMT)
GPS Location	Ave W 2nd Ave W 2nd Ave W 2nd Ave © Mapbox, © OpenStreetMap
	Lat: 39.720758 Long: -105.0314391
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes
--------------------------------------	-----



Error (%) 0.27	
-----------------------	--

Power System

Regulator Output Voltage (V)	13.93
Charging Current (mA)	280.00
Battery Voltage Quiet (V)	13.49
Battery Voltage Transmitted (V)	13.40

Transmitter

Desiccant, Program, Time, Bucket	Transmitter Checks
----------------------------------	--------------------

Radio

Watts Forward	3.90
Watts Reflected	0.00
Standing Wave Ratio	1.0000
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Depart Time	12:54 PM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance FC		
Location	Weir Gulch @ Julian St	
Station_ID	10032	
Technician(s)	ZJN,KGS	
Date	03/18/2020	
Time Arrive	05:04 PM (-6 GMT)	
GPS Location	Ave Knox Ct West Trail	W 2nd Ave © Mapbox, © OpenStreetMap
	Lat: 39.72079046 Long: -105.03138285	
Agency	UDFCD	

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes
--------------------------------------	-----



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	11.00
Error (%)	-0.89
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.25
Charging Current (mA)	37.00
Battery Voltage Quiet (V)	12.91
Battery Voltage Transmitted (V)	12.81

Transmitter

Transmitter Checks

Radio

Watts Forward	3.25
Watts Reflected	0.00
Standing Wave Ratio	1.0000
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Final Comments	Everything working well. Received test transmissions. Intake full of sediment
Depart Time	05:52 PM (-6 GMT)
Photos	



Station Maintenance Form

Location	Weir gulch @ Julian street
Station_ID	10032
Technician(s)	Kgs
Date	06/23/2020
Time Arrive	08:03 AM (-6 GMT)
GPS Location	Weir Gulch We W 2nd Ave Wand Ave
	9 4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
	Lat: 39.7205083360389 Long: -105.031338149863
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	4.00
Error (%)	-0.15
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.32
Charging Current (mA)	26.00
Battery Voltage Quiet (V)	13.43
Battery Voltage Transmitted (V)	13.37

Transmitter

|--|

Radio

Watts Forward	3.75
Watts Reflected	0.10
Standing Wave Ratio	1.3903
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Depart Time	08:45 AM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance Fo	
Location	Brantner Gulch @ Syracuse St
Station_ID	10041
Technician(s)	ZJN,KGS
Date	03/18/2020
Time Arrive	01:44 PM (-6 GMT)
GPS Location	Brantner Village F725th Dr E 124th Ave © Mapbox, © OpenStreetMap
	Lat: 39.92285158 Long: -104.89739235
Agency	UDFCD

Station Type

What type of station? Stream

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	9.00
Error (%)	-0.68
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	21.69
Charging Current (mA)	267.00
Battery Voltage Quiet (V)	12.69
Battery Voltage Transmitted (V)	12.63

Transmitter

|--|

Radio

Watts Forward	4.50
Watts Reflected	0.10
Standing Wave Ratio	1.3504
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Finishing Comments	
Final Comments	Everything working well. Received test transmissions
Depart Time	02:11 PM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance Fo	
Location	Brantner Gulch @ Syracuse
Station_ID	10041
Technician(s)	ZJN, EJH
Date	06/09/2020
Time Arrive	09:21 AM (-6 GMT)
GPS Location	Brantner Village © Mapbox © Mapbox © Mapbox © Mapbox
	Lat: 39.9229112 Long: -104.8974314
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	12.00
Error (%)	-1.00
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	11.94
Charging Current (mA)	71.00
Battery Voltage Quiet (V)	13.59
Battery Voltage Transmitted (V)	13.47

Transmitter

|--|

Radio

Watts Forward	4.25
Watts Reflected	0.10
Standing Wave Ratio	1.3624
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Finishing Commen	ts
Final Comments	Spider web holding tipping bucket up and top section clogged. Everything working well. Sent test transmissions.
Depart Time	09:53 AM (-6 GMT)
Photos	







Station Maintenance Form

Location	Brantner Gulch @ Syracuse
Station_ID	10041
Technician(s)	ZJN,EJH
Date	08/26/2020
Time Arrive	01:32 PM (-7 GMT)
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

|--|--|

Rain Sensor

Does the station have a rain sensor?	Yes
--------------------------------------	-----

Rain Gage Calibration

Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	7.00
Error (%)	-0.47
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.11
Charging Current (mA)	157.00
Battery Voltage Quiet (V)	13.27
Battery Voltage Transmitted (V)	13.16

Transmitter

Transmitter Checks	Program, Desiccant, Time, Bucket
--------------------	----------------------------------

Radio

Watts Forward	4.50
Watts Reflected	0.00
Standing Wave Ratio	1.0000



Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Final Comments	Everything working well
Depart Time	02:03 PM (-7 GMT)



Station Maintenance Form

Location	Big Dry Creek @ Thorncreek
Station_ID	10042
Technician(s)	ZJN,EJH
Date	08/26/2020
Time Arrive	02:15 PM (-7 GMT)
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks

Rain Sensor

Does the station have a rain sensor?	Yes	
--------------------------------------	-----	--

Rain Gage Calibration

Point ID	0
Tips During Calibration	13
Volume Added or Removed (mL)	-3.00
Error (%)	0.58
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	13.97
Charging Current (mA)	162.00
Battery Voltage Quiet (V)	13.44
Battery Voltage Transmitted (V)	13.29

Transmitter

Transmitter Checks	Desiccant, Program, Time, Bucket
--------------------	----------------------------------

Radio

Watts Forward	4.25
Watts Reflected	0.10
Standing Wave Ratio	1.3624




Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Final Comments	Everything working well. Beehive in bottom of top section. Bring spray and cover hole
Depart Time	02:51 PM (-7 GMT)



Station Maintenance Form



Station Type

What type of station? Stream

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks Funnel, S	lar_panel, Tipping_bucket
------------------------	---------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	13
Volume Added or Removed (mL)	-8.00
Error (%)	1.11
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.01
Charging Current (mA)	49.00
Battery Voltage Quiet (V)	13.97
Battery Voltage Transmitted (V)	13.85

Transmitter

|--|

Radio

Watts Forward	4.00
Watts Reflected	0.10
Standing Wave Ratio	1.3756
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Depart Time	11:03 AM (-6 GMT)
Photos	







Station Maintenance Form

Station Maintenance Fo	
Location	Big Dry Creek at Thorncreek
Station_ID	10042
Technician(s)	ZJN,KGS
Date	03/18/2020
Time Arrive	12:53 PM (-6 GMT)
GPS Location	Orncreek If Course Omcebox O
	Lat: 39.9367579 Long: -104.9839787
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	13
Volume Added or Removed (mL)	-5.00
Error (%)	0.80
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.22
Charging Current (mA)	56.00
Battery Voltage Quiet (V)	12.90
Battery Voltage Transmitted (V)	12.81

Transmitter

Transmitter Checks	Desiccant, Program, Time, Bucket
Transmitter emedic	Booloodin, Frogram, Timo, Buoket

Radio

Watts Forward	4.25
Watts Reflected	0.25
Standing Wave Ratio	1.6404
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Finishing Comme	
Final Comments	Everything working well. Received test transmissions. Bring wasp spray and something to cover hole on bottom of tipping bucket stand
Depart Time	01:27 PM (-6 GMT)
Photos	



Station Maintenance Form

Location	Coal Creek @ Twin Spruce
Station_ID	10049
Technician(s)	ZJN,KGS
Date	03/18/2020
Time Arrive	03:55 PM (-6 GMT)
GPS Location	© Mapbox, © OpenStreetMap Lat: 39.90019495 Long: -105.34282536
	Lat: 39.90019495 Long: -105.34282536
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Tipping_bucket, Solar_panel, Funnel
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes
--------------------------------------	-----



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	12.00
Error (%)	-1.00
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.71
Charging Current (mA)	38.00
Battery Voltage Quiet (V)	12.64
Battery Voltage Transmitted (V)	12.58

Transmitter

|--|

Radio

Watts Forward	5.00
Watts Reflected	0.10
Standing Wave Ratio	1.3294
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Finishing Comments	
Final Comments	PT working but offset keeps getting larger. Offset changed to 0.63 after 7 point test. Everything else working well. Received test transmissions.
Depart Time	04:20 PM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance Fo	
Location	Coal Creek @ Twin Spruce
Station_ID	10049
Technician(s)	ZJN,KGS
Date	06/30/2020
Time Arrive	10:04 AM (-6 GMT)
GPS Location	t Baptist Church © Mapbox, © OpenStreetMap
	Lat: 39.8999131 Long: -105.3429639
Agency	UDFCD

Station Type

What type of station? Stream	
------------------------------	--

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Tipping_bucket, Solar_panel
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	0
Tips During Calibration	12
Volume Added or Removed (mL)	11.00
Error (%)	-0.89
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.65
Charging Current (mA)	42.00
Battery Voltage Quiet (V)	12.81
Battery Voltage Transmitted (V)	12.74

Transmitter


Transmitter Checks

Radio

Watts Forward	5.00
Watts Reflected	0.00
Standing Wave Ratio	1.0000
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Finishing Comments	
Final Comments	PT reading way too low. Did a 6 point calibration and got an offset of -0.21. Changed from -0.63 New power lines right above and electrical boxes around the standpipe. Most likely what is effecting the transmissions. Decoded data, radio is working great.
Depart Time	10:50 AM (-6 GMT)
Photos	











Station Maintenance Form

Location	Coal Creek@ Twin Spruce
Station_ID	10049
Technician(s)	EJH/ZJN
Date	08/26/2020
Time Arrive	10:35 AM (-6 GMT)
GPS Location	† Prist Church © Mapbox, © OpenStreetMap
	Lat: 39.9001106 Long: -105.3428018
Agency	UDFCD

Station Type

What type of station?	Stream
-----------------------	--------

Stream Station Maintenance

Stream Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Rain Sensor

Does the station have a rain sensor?	Yes



Point ID	10049
Tips During Calibration	13
Volume Added or Removed (mL)	0.00
Error (%)	0.27
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	13.52
Charging Current (mA)	98.00
Battery Voltage Quiet (V)	12.96
Battery Voltage Transmitted (V)	12.86

Transmitter

Transmitter Checks

Radio

Watts Forward	4.50
Watts Reflected	0.00
Standing Wave Ratio	1.0000
Is the PT an SDI-12?	Yes
No calibration form necessary	Check to see if PT is working properly.

Depart Time	10:54 AM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance FC	
Location	Coal Creek @ Camp Eden
Station_ID	10050
Technician(s)	EJH/ZJN
Date	08/26/2020
Time Arrive	10:06 AM (-6 GMT)
GPS Location	10:06 AM (-6 GMT) Camp Eden Rd © Mapbox, © OpenStreetMap
	Lat: 39.9077214 Long: -105.3923191
Agency	UDFCD

Station Type

What type of station?	Precipitation
-----------------------	---------------

Precipitation Station Maintenance

Precipitation Maintenance

Items Cleaned

Clean Checks	Solar_panel, Funnel, Tipping_bucket
--------------	-------------------------------------

Point ID	10050
Tips During Calibration	13



Volume Added or Removed (mL)	-14.00
Error (%)	1.74
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.29
Charging Current (mA)	166.00
Battery Voltage Quiet (V)	13.68
Battery Voltage Transmitted (V)	13.60

Transmitter

Radio

Watts Forward	4.50
Watts Reflected	0.00
Standing Wave Ratio	1.0000

Stream Station Maintenance

No calibration form necessary	Check to see if PT is working properly.
-------------------------------	---

Depart Time	10:22 AM (-6 GMT)
Photos	



Station Maintenance Form

Station Maintenance Fo	1 1 1 1	
Location	Upper Coal Creek @ Camp Eden	
Station_ID	10050	
Technician(s)	ZJN,KGS	
Date	03/18/2020	
Time Arrive	03:29 PM (-6 GMT)	
GPS Location	Omephox	Camp Eden Rd® Mapbox, © OpenStreetMap
	Lat: 39.90777626 Long: -105.39236732	
Agency	UDFCD	

Station Type

What type of station?	Precipitation
-----------------------	---------------

Precipitation Station Maintenance

Precipitation Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Point ID	0
Tips During Calibration	13



Volume Added or Removed (mL)	-6.00
Error (%)	0.90
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.69
Charging Current (mA)	161.00
Battery Voltage Quiet (V)	12.82
Battery Voltage Transmitted (V)	12.77

Transmitter

Radio

Watts Forward	5.00
Watts Reflected	0.10
Standing Wave Ratio	1.3294

Stream Station Maintenance

No calibration form necessary	Check to see if PT is working properly.
-------------------------------	---

Final Comments	Everything working well. Received test transmissions.
Depart Time	03:50 PM (-6 GMT)
Photos	



Station Maintenance Form

Location	Upper coal creek @ camp Eden Road
Station_ID	10050
Technician(s)	Kgs
Date	06/23/2020
Time Arrive	
GPS Location	O9:42 AM (-6 GMT) Camp Eden Ra Camp Eden Ra © Mapbox, © OpenStreetMap
	Lat: 39.9077453613281 Long: -105.392500078404
Agency	UDFCD

Station Type

Precipitation Station Maintenance

Precipitation Maintenance

Items Cleaned

Clean Checks	Funnel, Solar_panel, Tipping_bucket
--------------	-------------------------------------

Point ID	0
Tips During Calibration	12



Volume Added or Removed (mL)	8.00
Error (%)	-0.58
Data Logger reads tips in both directions	checked

Power System

Regulator Output Voltage (V)	14.42
Charging Current (mA)	211.00
Battery Voltage Quiet (V)	13.65
Battery Voltage Transmitted (V)	13.59

Transmitter

Desiccant, Program, Time, Bucket

Radio

Watts Forward	5.00
Watts Reflected	0.00
Standing Wave Ratio	1.0000

Stream Station Maintenance

No calibration form necessary	Check to see if PT is working properly.
-------------------------------	---

Depart Time	09:46 AM (-6 GMT)
Photos	