MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 150

Service Log

Site Name: Nott Creek Date: 13-Aug-09 Time: 11:59
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location
BY R 0324
BY R 0202
9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0150-0012-0112-11011

Jumpers:

Eprom: B

Tx Freq: **169.525**

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

BY R 0324 13.00

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 150
 12:08
 1
 0

 150
 12:08
 2
 0

Problem: Battery low.

Action Taken: Replaced battery. TB OK.

MAINTENANCE RECORD **URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED**

Site ID:

200

Service Log

Site Name: Leyden Reservoir Date: 12-Aug-09 Time: 12:47

Technician: MZ Service Type: Inspection Status: Incomplete

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB partially blocked, cleaned out. TB OK. Could not receive transmissions at truck.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Upper Leyden Date: 12-Aug-09 Time: 13:58
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

220

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

310

Site ID:

Service Log

Site Name: Guy Hill Date: 13-Aug-09 Time: 12:46
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Site ID:

400

Service Log

Site Name: **Montview Park** Date: 12-Aug-09 Time: 10:09 Service Type: OneRain Service Ca Technician: DP Status: OK

Configuration Changes

Part # Location PT D 2113453 400 PT D 2672058 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error 403 0.011 -0.0129 0.004

Tx Maintenance

Ref V Part # Freq Err Deviation ROM Batt

Settings and Performance

Switches: Jumpers:

Eprom:

Tx Freq: Rx Freq:

Fwd Power: Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission							
Port	Time	Count	Measure		Predicted		
400	10:20	352			0		
400	10:20	353			0		
403	10:12	1847	9.08	psi	1955		
403	10:12	1431	7.04	psi	1515		
403	10:13	1036	5.09	psi	1096		
403	10:13	632	3.11	psi	668		
403	10:13	222	1.08	psi	232		
403	10:14	1031	5.07	psi	1036		
403	10:15	421	2.06	psi	422		

Problem:

Action Taken: Replaced PT, calibrated, repeatability OK. TB OK.

{Auto Entry: Calibrated sensor 403 by linear regression. Modified calibration data. New calibration [Slope(0.0113), Calibration Offset(-0.0129), Std Error(0.0040), Calibration

Date(8/12/2009 10:14:07 AM)]}.

Site Notes:

Follow-Up: Replace 1/2 pvc cap on intake.

MAINTENANCE RECORD **URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED**

Site ID:

410

Service Log

Site Name: **Kelly Dam** Date: 11-Aug-09 Time: 9:37 Service Type: OneRain Service Ca Technician: DP Status: OK

Configuration Changes

Part # Location PT D 2881227 410

Transducer Calibration

Sensor ID Slope Calib Offset Std Error 0.0054 413 0.015 -0.0124

Tx Maintenance

Ref V Part # Freq Err Deviation ROM Batt

Settings and Performance

Switches: Jumpers:

Eprom: Tx Freq:

Rx Freq:

Fwd Power: Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Tra	nsmission				
Port	Time	Count	Measure		Predicted
410	13:43	118			0
410	13:44	119			0
413	13:27	1386	9.14	psi	1917
413	13:28	1068	7.05	psi	1479
413	13:28	765	5.05	psi	1059
413	13:29	465	3.06	psi	643
413	13:29	163	1.07	psi	225
413	13:30	771	5.08	psi	772
413	13:31	306	2.00	psi	305

Problem:

Action Taken: Pulled in new PT, replaced 10 ft of PVC due to lightning damage, calibrated PT, repeatability OK.

TB OK.

{Auto Entry: Calibrated sensor 413 by linear regression. Modified calibration data. New

calibration [Slope(0.0152), Calibratio

n Offset(-0.0124), Std Error(0.0054), Calibration Date(8/11/2009 1:29:39 PM)]}.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT

440

Site ID:

ONERAIN INCORPORATED

Service Log

Site Name: Aurora FS#7 Date: 10-Aug-09 Time: 12:25
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location
BY R 0945 440
BY R 0286 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0440-3-D

Jumpers: Eprom:

Tx Freq: 169.525

Rx Freq:

 Fwd Power:
 4.9

 Rev Power:
 0.1

 SWR:
 1.33

Battery Tests

Battery # V Quiescent V Load

BY R 0945 13.09

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 440
 12:35
 1
 0

 440
 12:35
 2
 0

Problem:

Action Taken: Replaced battery and desiccant. RF OK. TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

510

Site ID:

Service Log

Site Name: Virginia Court Date: 10-Aug-09 Time: 11:16
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location
BY R 0344 510
BY R 0417 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0510-3-D

Jumpers: Eprom:

Tx Freq: **169.525**

Rx Freq:

 Fwd Power:
 4.8

 Rev Power:
 0.0

 SWR:
 1.1

Battery Tests

Battery # V Quiescent V Load

BY R 0344 13.04

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced battery and desiccant. TB OK. RF OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

520

Site ID:

Service Log

Site Name: Jewell Detention Date: 10-Aug-09 Time: 11:44
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location
BY R 0836 520
BY R 0340 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0520-3-D

Jumpers: Eprom:

Tx Freq: **169.525**

Rx Freq:

 Fwd Power:
 5.0

 Rev Power:
 0.0

 SWR:
 1.09

Battery Tests

Battery # V Quiescent V Load

BY R 0836 12.84

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 520
 11:57
 1
 0

 520
 11:57
 2
 0

Problem:

Action Taken: Replaced battery and desiccant. TB OK. RF OK. Cleaned TB Funnel.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

530

Site ID:

Service Log

Site Name: Denver FS #19 Date: 11-Aug-09 Time: 11:28
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0530-3-D

Jumpers: Eprom:

Tx Freq: **169.525**

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

540

Site ID:

Service Log

Site Name: Parker and Miss. Date: 11-Aug-09 Time: 11:15
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Site ID:

620

Service Log

Site Name: Quincy/Highline Time: 10:24 Date: 11-Aug-09 Technician: MZ Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Port Time

Test Transmission

Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

630

Site ID:

Service Log

Site Name: Temple Pond Date: 18-Aug-09 Time: 12:13
Service Type: OneRain Service Ca Technician: MZ Status: OK

Configuration Changes

Part # Location
BY R 0915 630
BY R 0415 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:
Jumpers:
Eprom:
Tx Freq:
Rx Freq:
Fwd Power:
Rev Power:
SWR:

Battery Tests

Battery # V Quiescent V Load

BY R 0915 13.01

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced Battery. TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Iliff Pond Date: 18-Aug-09 Time: 12:43
Service Type: OneRain Service Ca Technician: MZ Status: OK

Configuration Changes

Part # Location
BY R 0220 650
BY R 0217 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

650

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:
Jumpers:
Eprom:
Tx Freq:
Rx Freq:
Fwd Power:
Rev Power:

Battery Tests

SWR:

Battery # V Quiescent V Load

BY R 0220 13.37

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced Battery. TB OK.

MAINTENANCE RECORD **URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED**

710

Site ID:

Service Log

Site Name: Time: 12:48 **Horseshoe Park** Date: 10-Aug-09 Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Location Part # BY R 0849 710 BY R 0915 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Ref V Part # Freg Err Deviation ROM Batt

Settings and Performance

00E Switches: Jumpers: JB3&5

Eprom: R1.8 9CA1

Tx Freq: 169.525

Rx Freq:

Fwd Power: 4.8 Rev Power: 0.0 SWR: 1.1

Battery Tests

Battery # V Quiescent V Load

BY R 0849 13.12 Test Transmission

Port Time Count Measure Predicted 710 13:27 1 0 0 710 13:27 2

Problem:

Action Taken: Replaced Desiccant and battery. PT OK. Good hydraulic Contact. Flushed intake. Cleaned

funnel. RF OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

720

Site ID:

Service Log

Site Name: Confluence Pond Date: 10-Aug-09 Time: 13:43
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location
BY R 0510 720
BY R 0549 9000

Transducer Calibration

 Sensor ID
 Slope
 Calib Offset
 Std Error

 723
 0.012
 -0.2563
 0.0655

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches: **0720-00E**

Jumpers: C: JB6(12), J3,4 off;L:JB8,

Eprom: R 1.1.1 5C58

Tx Freq: **169.525**

Rx Freq:

Fwd Power: 5.0
Rev Power: 0.0

SWR: 1.09

Battery Tests

Battery # V Quiescent V Load

BY R 0510 12.90

Test Transmission							
Port	Time	Count	Measure		Predicted		
720	14:22	1			0		
720	14:23	2			0		
723	14:00	1725	8.80	psi	1745		
723	14:01	1551	7.96	psi	1581		
723	14:02	1256	6.31	psi	1255		
723	14:03	776	3.89	psi	779		
723	14:04	618	3.08	psi	617		
723	14:05	247	1.19	psi	245		

Problem:

Action Taken: {Auto Entry: Calibrated sensor 723 by linear regression. Modified calibration data. New

calibration [Slope(0.0119), Calibration Offset(-0.2563), Std Error(0.0655), Calibration

Date(8/10/2009 2:06:08 PM)]}.

Changed desisccant and battery. Replaced desiccant in PT box. Calibrated stream PT. Good

hydraulic contact. RF OK. TB OK.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

760

Site ID:

Service Log

Site Name: Mission Viejo Pk Date: 10-Aug-09 Time: 14:37
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location
BY R 0502 760
BY R 0416 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0760-3-D

Jumpers: Eprom:

Tx Freq: **169.525**

Rx Freq:

 Fwd Power:
 5.0

 Rev Power:
 0.0

 SWR:
 1.09

Battery Tests

Battery # V Quiescent V Load

BY R 0502 13.07

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced desiccant and battery. TB OK. RF OK. Cleaned TB funnel.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

830

Site ID:

Service Log

Site Name:Side Creek ParkDate:10-Aug-09Time:15:06Service Type:InspectionTechnician:SBStatus:OK

Configuration Changes

Part # Location
BY R 0802 830
BY R 0247 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 0830-3-D

Jumpers: Eprom:

Tx Freq: **169.525**

Rx Freq:

 Fwd Power:
 5.0

 Rev Power:
 0.0

 SWR:
 1.09

Battery Tests

Battery # V Quiescent V Load

BY R 0802 12.88

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 830
 15:15
 1
 0

 830
 15:16
 2
 0

Problem:

Action Taken: Replaced battery and desiccant. Cleaned TB funnel. TB OK. RF OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Site ID:

840

Service Log

Aurora FS 12 Site Name: Date: Time: 12:29 11-Aug-09 Technician: MZ Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1030

Service Log

Site Name: NREL/SERI Date: 12-Aug-09 Time: 12:02
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Apex Date: 13-Aug-09 Time: 13:38
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

1060

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 1060 13:41 299 0

1060 13:41 300 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

1330

Service Log

Site Name: Date: Time: 12:52 Roslyn 11-Aug-09 Technician: MZ Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

1330 Switches:

Jumpers:

Eprom: 9601-01-90 v. 3.9M

Tx Freq: 169.525

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1350

Site ID:

Service Log

Site Name: Chatfield Dam Date: 12-Aug-09 Time: 11:14
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Test Transmission

Time

Port

Part # Ref V Freg Err Deviation ROM Batt

Count

Measure Predicted

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

_, ..

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1360

Site ID:

Service Log

Site Name: Denver ZOO Date: 11-Aug-09 Time: 11:49
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

1370

Service Log

Site Name: Fire Station 13 Date: Time: 11:28 12-Aug-09 Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Test Transmission

Time

Port

Part # Ref V Freq Err Deviation ROM Batt

Count

Measure Predicted

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Problem:

Action Taken: TB OK.

Site Notes: Follow-Up:

08-Sep-09

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1520

Site ID:

Service Log

Site Name: Marston Lake Date: 19-Aug-09 Time: 12:17
Service Type: OneRain Service Ca Technician: SB/MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

2704 13:26 9 0

Problem:

Action Taken: Installed Comm Engine in place of High Sierra serial transmitter.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1520

Site ID:

Service Log

Site Name: Marston Lake Date: 28-Aug-09 Time: 11:17
Service Type: OneRain Service Ca Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Updated Program.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT

ONERAIN INCORPORATED

Service Log

Site Name: Lakewood CC Date: 17-Aug-09 Time: 9:55
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

1550

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 1550 9:58 374 0

1550 9:59 375 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

1600

Site ID:

Service Log

Site Name: 12-Aug-09 Time: 11:02 **Englewood Dam** Date: Service Type: OneRain Service Ca Technician: DP Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error 1603 0.01 -0.0127 0.0057

Tx Maintenance

Toot Tronomicaion

Ref V Part # Freq Err Deviation ROM Batt

Settings and Performance

Switches: Jumpers:

Eprom:

Tx Freq: Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

rest rra	nsmission				
Port	Time	Count	Measure		Predicted
1600	15:05	236			0
1600	15:06	237			0
1603	14:52	2047	9.09	psi	2179
1603	14:52	1671	7.08	psi	1703
1603	14:53	1233	5.23	psi	1262
1603	14:54	728	3.09	psi	752
1603	14:54	484	2.05	psi	507
1603	14.57	2047	8 70	nsi	2086

Problem:

Action Taken: Pulled new PT, calibrated, repeatability OK, good hydraulic contact. TB OK.

{Auto Entry: Calibrated sensor 1603 by linear regression. Modified calibration data. New calibration [Slope(0.0098), Calibration Offset(-0.0127), Std Error(0.0057), Calibration

Date(8/12/2009 2:57:37 PM)]}.

Site Notes: Buried junction box about 10 ft. N of west edge of structure.

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 1640

Service Log

Site Name: SPR at Union Ave. Date: 12-Aug-09 Time: 10:55
Service Type: Repair Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Reprogrammed Sutron 8200 with proper ID for stage (1643)

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: SPR at Union Ave. Date: 19-Aug-09 Time: 10:16
Service Type: OneRain Service Ca Technician: SB/MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

1640

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Uploaded new program in the Sutron. USGS takes stage reading every 15 minutes. Our

equipment reads every 5 Min.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1640

Site ID:

Service Log

Site Name: SPR at Union Ave. Date: 11-Aug-09 Time: 10:05
Service Type: OneRain Service Ca Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Repaired wiring link from USGS Sutron SatLink to Sutron 8200/Tx. Stage reporting OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

1660

Site ID:

Service Log

Site Name: SPR at Henderson Date: 24-Aug-09 Time: 10:19
Service Type: OneRain Service Ca Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 1660 10:35 70 0

1660 10:36 72 0

Problem: Quit 8/18/09

Action Taken: Radio bad, received locally but no real power, replaced, RF OK. TB OK.

MAINTENANCE RECORD Sit

Site ID: 1710

ONERAIN INCORPORATED

Service Log

Site Name: Shop Creek Date: 12-Aug-09 Time: 10:00
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

 Part #
 Location

 BY R 0416
 1710

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:
Jumpers:
Eprom:
Tx Freq:
Rx Freq:
Fwd Power:

Battery Tests

Rev Power: SWR:

Battery # V Quiescent V Load

BY R 0416 13.03

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced Battery. TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Shop Creek Date: 11-Aug-09 Time: 10:54
Service Type: Inspection Technician: MZ Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

1710

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

2260

Service Log

Site Name: Date: Time: 10:27 **Brook Forest** 14-Aug-09 Technician: DP Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

2260-0012-0112-11011 Switches:

Jumpers:

Eprom: В

Tx Freq: 169.525

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted 2260 10:28 269 0 2260 270 0 10:28

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name:Kinney PeakDate:14-Aug-09Time:11:01Service Type:InspectionTechnician:DPStatus:OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

2280

0

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

11:04

2280

Port Time Count Measure Predicted 2280 11:03 335 0

336

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 2310

Service Log

Site Name: Genesee Village Date: 14-Aug-09 Time: 9:39
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 2310-0012-0112-11011

Jumpers:

Eprom: B

Tx Freq: **169.525**

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 2310
 9:42
 339
 0

 2310
 9:47
 340
 0

Problem:

Action Taken: Topsection funnel and TB funnels plugged, cleared, TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Choke Cherry Res Date: 21-Aug-09 Time: 13:15
Service Type: OneRain Service Ca Technician: DP/GH Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

2320

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 2320
 14:21
 30
 0

 2320
 14:22
 31
 0

Problem:

Action Taken: Replaced repeater with original (single radio) with Ritron radio, adjusted squelch, with cavity filter

in line. TB OK.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

2340

0

Site ID:

Service Log

Site Name: El Rancho Date: 14-Aug-09 Time: 9:57
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

9:58

Port Time Count Measure Predicted 2340 9:58 264 0

265

2340

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

2350

0

Site ID:

Service Log

Site Name: Idledale Date: Time: 11:46 14-Aug-09 Technician: DP Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

V Quiescent V Load

Test Transmission

11:48

2350

Port Time Count Measure Predicted 2350 11:47 332 0

333

Battery #

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT

2360

ONERAIN INCORPORATED

Service Log

Site Name: Indian Hills Date: 14-Aug-09 Time: 11:30
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches: 2360-0012-0112-11011

Jumpers:

Eprom: B

Tx Freq: **169.525**

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 2360
 11:31
 284
 0

 2360
 11:31
 285
 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Red Rocks Date: 21-Aug-09 Time: 14:40
Service Type: OneRain Service Ca Technician: DP Status: OK

Configuration Changes

Part # Location
BY R 0919 2370
BY R 0211 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

2370

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:
Jumpers:
Eprom:
Tx Freq:
Rx Freq:
Fwd Power:
Rev Power:

Battery Tests

SWR:

Battery # V Quiescent V Load

BY R 0919 13.05

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Replaced battery due to testing performed. TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4010

Site ID:

Service Log

Site Name: Crescent Rain Date: 14-Aug-09 Time: 13:00
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4010 13:01 202 0

4010 13:01 203 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

4020

Site ID:

Service Log

Site Name: Date: Time: 13:14 **Rio Grande Rain** 14-Aug-09 Technician: DP Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Test Transmission

Time

Port

Part # Ref V Freg Err Deviation ROM Batt

Count

Measure Predicted

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Problem:

Action Taken: TB OK.

Site Notes: Follow-Up:

08-Sep-09

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name:Red Garden RainDate:27-Aug-09Time:13:34Service Type:AdministrationTechnician:SBStatus:OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4030

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID:

4040

Service Log

Site Name: Martin Gulch Date: 14-Aug-09 Time: 14:26
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4040 14:27 103 0

4040 14:27 103 0 4040 14:27 104 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4050

Site ID:

Service Log

Site Name: Walker Ranch Date: 14-Aug-09 Time: 14:06
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 4050
 14:08
 152
 0

 4050
 14:09
 153
 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD S URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4060

Service Log

Site Name: Lakeshore Date: 14-Aug-09 Time: 13:57
Service Type: Inspection Technician: DP Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Service Log

Site Name: **Bear Peak** Date: Time: 14:52 14-Aug-09 Technician: DP Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4070

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted 0

4070 14:55 198

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Twin Sisters Date: 20-Aug-09 Time: 9:58
Service Type: OneRain Service Ca Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4080

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4090

Site ID:

Service Log

Site Name: Magnolia Date: 20-Aug-09 Time: 10:30
Service Type: OneRain Service Ca Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4100

Service Log

Site Name: Filter Plant Date: 17-Aug-09 Time: 13:38
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4100 13:38 60 0

4100 13:39 61 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD S URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4110

Service Log

Site Name: Betasso Date: 17-Aug-09 Time: 13:20
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD S URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4130

Service Log

Site Name: Swiss Peaks Date: 17-Aug-09 Time: 13:58
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4130 14:02 148 0

4130 14:03 149 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Site ID:

4140

Service Log

Site Name: Time: 10:52 Logan Mill Date: 18-Aug-09 Technician: DP/SB Service Type: Inspection Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted 4140 10:52 557 0

4140 558 0 10:53

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Gold Hill Date: 18-Aug-09 Time: 11:28
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4150

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission
Port Time Count Measure Predicted

 4150
 11:34
 166
 0

 4150
 11:34
 167
 0

 4150
 11:35
 168
 0

Problem:

Action Taken: Topsection funnel plugged, cleared, TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4160

Service Log

Site Name: Sunshine Date: 18-Aug-09 Time: 11:49
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4160 11:52 160 0

4160 11:53 177 0

Problem:

Action Taken: TB OK. (decoder error).

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

4170

Service Log

Site Name: Date: Time: 14:26 **Pinebrook** 27-Aug-09 Technician: SB Service Type: Administration Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Test Transmission

Time

Port

Part # Ref V Freg Err Deviation ROM Batt

Count

Measure Predicted

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Problem:

Action Taken: TB OK

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Gold Lake Date: 18-Aug-09 Time: 13:01
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4180

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4180 13:02 144 0

 4180
 13:02
 144
 0

 4180
 13:03
 145
 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4190

Site ID:

Service Log

Site Name: Slaughterhouse Date: 25-Aug-09 Time: 10:56
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4190 11:06 143 0

4190 11:11 144 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Lazy Acres Date: 25-Aug-09 Time: 10:30
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4200

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4200 10:32 151 0

4200 10:32 151 0 4200 10:32 152 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Flings Date: 18-Aug-09 Time: 13:24
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4220

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4220 13:24 184 0

4220 13:24 164 0 4220 13:25 185 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT

ONERAIN INCORPORATED

Service Log

Site Name: Golden Age Date: 25-Aug-09 Time: 11:41
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

4230

Tx Maintenance

Test Transmission

Time

Port

Part # Ref V Freg Err Deviation ROM Batt

Count

Measure Predicted

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4240

Service Log

Site Name: Sunset Date: 18-Aug-09 Time: 12:17
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4240 12:18 124 0

4240 12:18 125 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID:

4250

Service Log

Site Name: Geer Canyon Date: 20-Aug-09 Time: 15:38
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4260

Service Log

Site Name: Taylor Mountain Date: 20-Aug-09 Time: 12:47
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4270

Service Log

Site Name: Cannon Mountain Date: 18-Aug-09 Time: 13:47
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

4270 14:02 150 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4290

Site ID:

Service Log

Site Name: Red Hill Date: 20-Aug-09 Time: 15:04
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

 Switches:
 4290-00E

 Jumpers:
 C:J5 off

 Eprom:
 R 1.8 9CA1

 Tx Freq:
 169.500

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4300

Site ID:

Service Log

Site Name: Big Elk Park Date: 26-Aug-09 Time: 12:45
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4300 12:46 149 0

4300 12:47 150 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Johnny Park Date: 26-Aug-09 Time: 11:36
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4310

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4310 11:37 183 0

4310 11:37 183 0 4310 11:37 184 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4330

Service Log

Site Name: Hansen Date: 25-Aug-09 Time: 9:36
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

 Switches:
 4330-00E

 Jumpers:
 C: J5 off

 Eprom:
 R 1.8 9CA1

 Tx Freq:
 169.500

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

 Port
 Time
 Count
 Measure
 Predicted

 4330
 9:37
 98
 0

 4330
 9:37
 99
 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4340

Site ID:

Service Log

Site Name:RiversideDate:25-Aug-09Time:13:14Service Type:InspectionTechnician:DP/SBStatus:OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4340 13:16 122 0

4340 13:16 122 0 4340 13:16 123 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4350

Site ID:

Service Log

Site Name: Conifer Hill Date: 20-Aug-09 Time: 13:31
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4360

Service Log

Site Name: Justice Center Date: 17-Aug-09 Time: 14:31
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4360 14:42 661 0

4360 14:42 661 0 4360 14:43 662 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Bridge Date: 17-Aug-09 Time: 11:12
Service Type: OneRain Service Ca Technician: DP/SB Status: OK

Configuration Changes

Part # Location
PT D 2841951 4420
BY CSR 0204 4420
BY R 0837 9000

Transducer Calibration

Sensor ID Slope Calib Offset Std Error 4423 0.011 0.0176 0.0061

Site ID:

4420

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches: Jumpers: Eprom: Tx Freq: Rx Freq:

Fwd Power:
Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission Port Time Count Measure Predicted 4423 12:34 1870 9.07 psi 1834 4423 12:35 1425 1451 7.05 psi 1026 4423 12:35 1044 5.08 psi 4423 12:35 623 3.03 psi 612 4423 12:36 220 216 1.07 psi 4423 12:37 1044 5.07 psi 1043 4423 12:37 430 430 2.09 psi

Problem:

Action Taken: Pulled in new PT and calibrated, repeatability OK, good hydraulic contact. Replaced battery.

{Auto Entry: Calibrated sensor 4423 by linear regression. Modified calibration data. New calibration [Slope(0.0112), Calibration Offset(0.0176), Std Error(0.0061), Calibration

Date(8/17/2009 12:36:36 PM)]}.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4490

Site ID:

Service Log

Site Name: Apple Valley Date: 25-Aug-09 Time: 14:02
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

4490 14:11 189 0

Problem:

Action Taken: TB OK. Top section funnel plugged, cleared.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4510

Service Log

Site Name: Pinewood Spring Date: 26-Aug-09 Time: 11:03
Service Type: Inspection Technician: DP/SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4510 11:07 174 0

4510 11:07 174 0 4510 11:07 175 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4520

Site ID:

Service Log

Site Name:Eagle RidgeDate:26-Aug-09Time:10:20Service Type:InspectionTechnician:DP/SBStatus:OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted 4520 10:23 1299 0

4520 10:24 1300 0

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name: Winiger Ridge Date: 20-Aug-09 Time: 11:11
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

4530

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Site ID: 4550

Service Log

Site Name: Boulder Jail Date: 27-Aug-09 Time: 12:01
Service Type: Administration Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

Site Notes:

Follow-Up: Watch for wasps!

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4570

Site ID:

Service Log

Site Name: St. Antons Date: 20-Aug-09 Time: 11:50
Service Type: Inspection Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK

MAINTENANCE RECORD Site ID: URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4580

Service Log

Site Name: Broadway Date: 26-Aug-09 Time: 15:34
Service Type: Administration Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: The reference level at Head was changed from -.12 to -.05. This was changed so that the PT

matched the staff guage on site. Kim Hutton of Boulder had requested the change since the PT

was .07 off from the staff.

Site Notes:

Follow-Up:

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT **ONERAIN INCORPORATED**

Site ID:

4810

Service Log

Site Name: Time: 12:35 **Shanahan Ridge** Date: 27-Aug-09 Technician: SB Service Type: Administration Status: OK

Configuration Changes

Part # Location Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

4820

Site ID:

Service Log

Site Name: Dowdy Draw Date: 27-Aug-09 Time: 13:02
Service Type: Administration Technician: SB Status: OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Tx Maintenance

Part # Ref V Freg Err Deviation ROM Batt

Settings and Performance

 Switches:
 4820-00E

 Jumpers:
 C: J5 off

 Eprom:
 R 1.8 9CA1

 Tx Freq:
 169.500

Rx Freq: Fwd Power: Rev Power: SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: Cleaned Funnel. TB OK.

MAINTENANCE RECORD URBAN DRAINAGE AND FLOOD CONTROL DISTRICT ONERAIN INCORPORATED

Service Log

Site Name:Fairview PeakDate:28-Aug-09Time:11:13Service Type:AdministrationTechnician:SBStatus:OK

Configuration Changes

Part # Location

Transducer Calibration

Sensor ID Slope Calib Offset Std Error

Site ID:

4860

Tx Maintenance

Part # Ref V Freq Err Deviation ROM Batt

Settings and Performance

Switches:

Jumpers:

Eprom:

Tx Freq:

Rx Freq:

Fwd Power:

Rev Power:

SWR:

Battery Tests

Battery # V Quiescent V Load

Test Transmission

Port Time Count Measure Predicted

Problem:

Action Taken: TB OK.